5- PULIZIA **CLEANING**

- I) Per la pulizia quotidiana usare unicamente acqua e sapone e asciugare con un panno morbido.
 - Non usare altri detergenti o abrasivi che potrebbero danneggiare o deteriorare la superficie cromata.
- GB For the daily cleaning , you must use water and soap only and you have to wipe it With a soft cloth.
 - Do not use any other abrasive cleanser which can damage the surface.

6- CONDIZIONI DI LAVORO **JOB CONDITIONS**

- I) Pressione Min. di funzionamento 1 Bar
 - Pressione Max. di funzionamento 5 Bar
 - Pressione di funzionamento raccomandata 2÷4 Bar

 - Temperatura Max. acqua calda 80° C
 Temperatura acqua calda raccomandata 60° C
 Per pressioni superiori a 5 Bar installare un riduttore di pressione.
- GB Minimal pressure of operation 1 Bar Maximal pressure of operation 5 Bar

 - Pressure of operation registered letter 2÷4 Bar
 - Temperature maximum hot water $80^{\circ}~\mathrm{C}$

 - Temperature warm water registered letter 60° C
 For advanced pressures to 5 Bars to install a pressure reducer



Via Brughiere,50 Fax.+39.0322.967797 I- 28017 San Maurizio No e-mail :huber@huber-on-line.com Tel.+39.0322.967783

ICON

COMPLETO DOCCIA DUPLEX CON PRESA D'ACQUA WALL ELBOW & FLEXIBLE SHOWER KIT





